

Protected

4

OBO
BETTERMANN

Only a matching system offers the best protection.

4 Surge protection

According to IEC 60364-4-44 and IEC 60364-5-53, surge protection is frequently mandatory



1 Lightning protection

IEC/EN 62305 and state and model building regulations require lightning protection




3 Equipotential bonding

IEC/EN 60364-1 requires protection against electric shocks



2 Earthing

IEC/EN 62305 requires foundation earth electrodes



Customer Service



South Africa

O-line (Pty) Ltd Johannesburg

Reg No 1982/000082/07
P.O. Box 6457
Johannesburg 2000
14/16 Prop Street
Selby Ext. 11
Johannesburg 2001
South Africa
Tel: (+27) 011-378-3700
email: o-line@o-line.com

O-line Pretoria

P.O.Box 2039
Silverton 0127
The Willows Business Park
219 Battery Street
Silverton
South Africa
Tel: (+27) 012-803-1803
email: o-linepta@o-line.com

O-line Kwazulu-Natal

Reg No 1982/000082/07
P.O.Box 2534
New Germany 3620
13 Young Road
Westmead 3610
South Africa
Tel: (+27) 031-705-6355
email: o-linekzn@o-line.com

O-line Cape Town

Reg No 1985/000416/07
P.O.Box 506
Eppindust 7475
Unit 1, 17 Hewett Avenue
Epping Industria 2
7460
Tel: (+27) 021-531-9071
email: o-linecpt@o-line.com

O-line Gqeberha

P.O.Box 1352
Gqeberha 6000
Unit 10, BMI Complex
26 Patterson Road
North End
Gqeberha 6001
South Africa
Tel: (+27) 041-486-3674
email: o-lineepe@o-line.com

O-line Bloemfontein

P.O.Box 29809
Danhof 9310
Eland Street
Eland Industrial Park
Unit 11
Quaggafontein
Bloemfontein 9301
South Africa
Tel: (+27) 051-432-0707
email: o-linebfn@o-line.com

International

O-line Mocambique Limitada

Reg No. 2009/1001240/68 Rua
Beliluana
Parcela 510
Djuba, Matola- Rio
Tel: (+258) 21 730 243
email: o-linemz@o-line.com

OBO Bettermann Ghana Reg

No. CS036372016
Plot No. 53
Flower Pot
Spintex Road
Accra
Ghana
Tel: (+233) 501 522 488 email:
obo.ghana@obo-bettermann.com